

Vapormax 1 Instructions

Preparing:

Charge your Vapormax batter for 2hours, your charger will be removed while charging and will turn green once the battery is full

To load your Vapormax

Remove the chamber connector from the ceramic heating chamber

Fill the ceramic heating chamber with your herbs. Use the packing tool to gently pack the chamber with your herbs(do not overpack)

Screw the chamber connector back into the ceramic heating chamber with your vapormax connected you are now ready to vapor!

Initial Charge:

We recommend charging your Vapormax for at least 6 hours on the first charge, This will condition the battery for future battery life span

Charging:

Charge your Vapormax battery for approximately 2 hours. The LED will display while charge and full. Remove battery from charger once the battery is full as shows. When the LED display shows empty the device needs to be charged

Several Charging Options:

USB Charger-----connect directly to any USB port

Wall adapter-----works in conjunction with the USB charger

Car charger----works in conjunction with the USB charger

Tips:

- 1.For best results do not pack the ceramic heating chamber too tightly with your herbs. This will ensure easy air flow passage for heating
- 2.Please remember to hold the power button down for at least two seconds before inhaling to activate the heating element
- 3.Between use, wait three seconds before reactivating the device
- 4.In the event that vapor is not being released, use the packing tool gently to rotote the herbs within the chamber
- 5.For best results, break the herbs up by hand or grind them. Be sure to remove all steams and/or seeds before filling the heating chamber.